Historic Resource Survey Form
PENNSYLVANIA HISTORICAL AND MUSEUM COMMISSION Bureau for Historic Preservation

	Key #
ER#	

1					
Name, Location and Ownership					
HISTORIC NAME Lehigh Slate Company Mantel Factory					
CURRENT/CO	CURRENT/COMMON NAME Charles H. Mantz Inc				
STREET ADD	ORESS 26 Factory Str	reet			<b>ZIP</b> <u>18080</u>
LOCATION	Slatington				
MUNICIPALIT	Y Slatington		cou	INTY Lehigh	
TAX PARCEL	#/YEAR 5562230	97425 1/2013	uso	S QUAD Palmerto	on Quadrangle 2016
OWNERSHIP	⊠ Private				
	☐ Public/Loc	cal ☐ Public/Co	unty 🗌 Public/State [	☐ Public/Federal	
OWNER NAM	IE/ADDRESS Ruthan	n Mantz, 465 Kue	hner Ave, Slatington PA		
CATEGORY (	OF PROPERTY 🛛 🗎	Building 🗌 Site	☐ Structure ☐ Obj	ect 🗌 District	
TOTAL NUME	BER OF RESOURCES	One			
Function		for functions, c	ategories and types)		
	Historic Function		Subcategory		Particular Type
	Industry		Manufacturing Facility		Factory
	Current Function		Subsetement		Postinulas Tura
	Commerce/Trade		Subcategory Warehouse		Particular Type Warehouse
	Commerce/ Trade		w archouse		warehouse
					<del></del>
					<del></del>
A 1.4					
Architect	tural/Property	Information			
ARCHITECTU	JRAL CLASSIFICATIO	N			
	Mid-19 <sup>th</sup> Century		Other		
EXTERIOR M	ATERIALS and STRU		Λ		
	Foundation	Slate/concrete			
	Walls	Slate/concrete			
	Roof	<u>Tin</u>			
	Other	Stucco	4 1		
	Structural System	<u>Timber – post an</u>	u beam		
	WINTH 80 (feet) or	(# have)	DEPTH 40 (feet) or	(# rooms)	STORIES/HEIGHT 2+

	Key #
ER#	

Property Features
Setting Industrial
Ancillary Features
<b>Acreage</b> $0.60$ (round to nearest tenth)
Historical Information
Year Construction Began 1859 ⊠ Circa Year Completed 1859 ⊠ Circa
· —
Date of Major Additions, Alterations 1904 ⊠ Circa □ □ Circa □ □ Circa □ □ Circa
Basis for Dating Documentary Physical
Explain Sanford Insurance maps and information from The Slatington News
Cultural/Ethnic Affiliation(s) <u>n/a</u>
Associated Individual(s) Robert McDowell, one of the founders of the Lehigh Slate Company
Associated Event(s)
Architect(s) <u>Unknown</u>
Builder(s) <u>Unknown</u>
Submission Information
Previous Survey/Determinations Slatington Historic District (National Register of Historic Places), section 7 page 3 and listed as
resource no. 36.
Threats ☑ None ☐ Neglect ☐ Public Development ☐ Private Development ☐ Other
Explain
This submission is related to a ☐ non-profit grant application ☐ business tax incentive
☐ NHPA/PA History Code Project Review ☐ other
Preparer Information
•
Name & Title Dr. Charles Evans, professor and assistant dean of history
Date Prepared May 2017 Project Name
Organization/Company Northern Virginia Community College
Mailing Address 2415 Bugle Lane, Reston, VA 20191
Phone 703.391 7414 Email charles.t.evans@gmail.com

	Key #	
ER#		

National Rec		ation rector, Agency Consultant, or	for Project Review	vs ONLY.)
, , , , , , ,	-	ole (due to ☐ lack of significance a	-	·
	☐ Eligible	Area(s) of Significance	ind/or in lack or integri	• • • • • • • • • • • • • • • • • • • •
		Criteria Considerations		Period of Significance
	☐ Contribut	tes to Potential or Eligible District	District Name	-
Bibliography	/ (Cite major ret	ferences consulted. Attach addit	tional page if needed	d.)
Various indent  [Articles of In This includes I Slatington," pp "A Draft of the New Illustrate	corporation Benjamin Silli 9-18. intended Bor	or Slatington (1896, 1902, gage records, Lehigh Country of the] Lehigh Slate Control man, Jr., "Report on the Strough of Slatington Lehigh ehigh County, Pennsylva	inty, Pennsylvan mpany, Lehigh ( Slate Quarries of County" (1864) ania (1876)	ia County, Pennsylvania, 1857 (1857) the Lehigh Slate Company at
The Geology (1883)	of Lehigh an	d Northampton Counties	s: Second Geol	ogical Survey, Report of Progress
History of the "Historical Ske Albert Koons,	tch of the Bo Illustrated H , A History o	rough of Slatington" in Ord istory of the Lehigh Vall of Lehigh County, Penns	dinances of the ey (1893)	alth of Pennsylvania (1884) Borough of Slatington (1892)
Charles H. Be	hre, Jr., Slate	in Pennsylvania (1933)		
		County Pennsylvania Ge		
"Slatington His	toric District,	" National Register of Histo	oric Places Regi	stration Form (2004)

Additional Information The following must be submitted with form. Check the appropriate box as each piece is completed and attach to form with paperclip.
☐ Narrative Sheets—Description/Integrity and History/Significance (See Instructions, pages 13-14)
☐ Current Photos (See Instructions, page 10)
☐ Photo List (See Instructions, page 11)
☐ Site Map (sketch site map on 8.5x11 page; include North arrow, approximate scale; label all
resources, street names, and geographic features; show exterior photo locations; See Instructions, page 11)
☐ Floor Plan (sketch main building plans on 8.5x11 page; include North arrow, scale bar or length/width
dimensions; label rooms; show interior photo locations; See Instructions, page 11)
☐ USGS Map (submit original, photocopy, or download from TopoZone.com; See Instructions, page 12)

## **Send Completed Form and Additional Information to:**

National Register Program
Bureau for Historic Preservation/PHMC
Keystone Bldg., 2<sup>nd</sup> Floor
400 North St.
Harrisburg. PA 17120-0093

	Key #
ER#_	

## Photo List (Item 33)

See the Instructions for more information regarding photos and the photo list. In addition to this photo list, create a photo key for the site plan and floor plans by placing the photo number in the location the photographer was standing on the appropriate plan. Place a small arrow next to the photo number indicating the direction the camera was pointed. Label individual photos on the reverse side or provide a caption underneath digital photos.

Photographer name Charles Evans

Date 29 April 2017

Photo #	Photo Subject/Description	Camera Facing
	The following are exterior photos of the building.	
1	Exterior photo taken from the northwest facing southeast and showing west and north sides of the building. (1Viewfromnorthwest.tif)	southeast
2	Exterior photo taken from the southeast facing northwest and showing east and south sides of the building. Difficult to get this view because of the close proximity of Trout Creek. (2Viewfromsoutheast.tif)	northwest
3	Exterior photo of east side of the building. (3East.tif)	west
4	Exterior photo of the west side of the building. (4West.tif)	east
5	Exterior photo of the south side of the building. This photo had to be photomerged from two photos because the proximity of Trout Creek did not allow a photo from far enough away to capture entire side. (5South.tif)	north
6	Exterior photo of the north side of the building. This photo also had to be photomerged from two photos to capture the entire side. (6North.tif)	south
7	Exterior photo of the northeast corner of the building showing detail of the wall's slate construction. (7Northeastcorner.tif)	southwest
8	Exterior photo close-up of the northeast corner of the building showing exposed wire mesh used for stucco. (8Northeastcorermsh.tif)	southwest
9	Exterior photo of storage/coal bins on property. (9bins.tif)	southeast
	The following are interior photos on the ground floor.	
10	Interior ground floor photo of wall and its slate/concrete structure. (10.tif)	west
11	Interior ground floor photo of possible unused former coal door. (11.tif)	northwest
12	Interior ground floor photo of blocked window. (12.tif)	northwest
13	Interior ground floor photo of massive floor joist for first floor, spanning entire building width of almost 50 feet. (13.tif)	east
14	Interior ground floor photo of blocked window. (14.tif)	south
15	Interior ground floor photo of south wall and blocked windows. (15.tif)	southeast
16	Interior ground floor photo of massive floor joist for first floor. (16.tif)	southeast
17	Interior ground floor photo of northeast corner of building and blocked windows (17.tif)	northeast
18	Interior ground floor photo of east wall and current main door/entrance (18.tif)	east
19	Interior ground floor close-up photo of wall construction. (19.tif)	east
20	Interior ground floor another photo of first floor joist. Here there is an iron rod fixed into the joist. The rod extends through above floor to roof joists. Theory is that rod was added when weight of slate roof was removed. (20.tif)	south
21	Interior ground floor photo showing detail of south wall. (21.tif)	south
22	Interior ground floor photo of east wall showing interior chimney, currently unused. (22.tif)	east
23	Interior ground floor photo showing depth of the wall construction, approximately 28 inches (23.tif)	south

	Key #	
ER#		

Photo #	Photo Subject/Description	Camera Facing
24	Interior ground floor photo of floor joist. (24.tif)	south
25	Interior ground floor photo of wall at current door opening on the east wall. (25.tif)	east
26	Interior ground floor photo of rails in the header of the blocked door in the south wall. (26.tif)	south
	The following are interior photos on the first floor.	
27	Interior first floor photo of truss work for roof. (27.tif)	south
28	Interior first floor photo of truss work for roof. (28.tif)	south
29	Interior first floor photo of truss work, showing rod extending from floor through roof truss work. See photo #20. (29.tif)	east
30	Interior first floor photo of west wall. (30.tif)	west
31	Interior first floor photo showing the current furnace and the exterior of office space in northeast corner. (31.tif)	north
32	Interior first floor photo showing exterior of the office space and roof trusses. (32.tif)	north

	Key #
ER#_	
	_

Photo #	Photo Subject/Description	Camera Facing
33	Interior first floor photo showing a typical window. (33.tif)	east
34	Interior first floor photo showing the south wall looking east. (34.tif)	east
35	Interior first floor photo showing some of the original roof planking for the former slate roof. (35.tif)	south
36	Interior first floor photo of east wall with good view of some roof trussing. (36.tif)	east
37	Interior first floor photo view of floor planking. (37.tif)	southeast
38	Interior first floor photo of blocked window on east side. (38.tif)	east
39	Interior first floor photo of roof truss at south wall. (39.tif)	south
40	Interior first floor photo of roof truss at north wall. (40.tif)	northeast
41	Interior first floor photo of south wall looking west. (41.tif)	west
42	Interior first floor photo of truss with additional attachments. (42.tif)	north
43	Interior first floor photo at east wall showing ladder remnant. (43.tif)	east
44	Interior first floor photo looking at chimney (no longer used) on inside of west wall. (44.tif)	west
	The following photos are of graffiti found on walls and trussed on the first floor.	
45	Interior first floor photo of name S. W. Remaley (Samuel William Remaley, 1865-1931) on interior chimney. (45.tif)	northwest
46	Interior first floor photo of truss with the name W. Bachman (Walter Bachman, 1845-1904). He was the longtime manager of this slate factory. (46.tif)	west
47	Interior first floor photo of truss with the name Preston H. Remaley (Preston Harrison Remaley, 1888-1975). (47.tif)	west
48	Interior first floor photo of truss with the name Robt Souerwine (Robert Souerwine, 1884-1970). (48.tif)	east
49	Interior first floor photo of name Elmer E. Oswald on west wall (Elmer Oswald, 1864-1936). (49.tif)	west
50	Interior first floor photo of graffiti on west wall. (50.tif)	west
51	Interior first floor photo of the name Wm. Best on west wall (William A. Best?, 1868-1921). (51.tif)	west
52	Interior first floor photo of the name Russell W. Everett on west wall (Russell W. Everett, 1892-1984). (52.tif)	west
53	Interior first floor photo of graffiti on west wall. (53.tif)	west
54	Interior first floor photo of graffiti on west wall and name P. McConichie (Peter MacConichie, 1868-?, owner of the foundry and machine shop to the immediate west of this bulding.). (54.tif)	east
55	Interior first floor photo of graffiti on west wall (SHS class of 09) and name W. E. Bachman (Warren E. Bachman, 1890-1951). He was a son of Walter Bachman. See photo 46. (55.tif)	west
56	Interior first floor photo of graffiti on west wall with name M. Bachman (Morris Bachman, 1880-1962). He was another son of Walter Bachman. See photo 46. (56.tif)	west
57	Interior first floor photo of graffiti on interior chimney. (57.tif)	west
	The following are exterior photos of the general site around the building. Photo Credits Bruce Roberts, May 2017.	
58	Exterior view, looking east from the building. (58 View east 1.tif)	east
59	Exterior view, looking west from the building (59 View west 1.tif)	west
60	Exterior view, looking south from the building, across Trout Creek to the former Lehigh Valley Railroad Slatedale branch, now The Slate Heritage Trail. The Mantel Quarry was just a little east of this location. (59 View west 1.tif)	south

	Key #	
ER#		

Photo #	Photo Subject/Description	Camera Facing
61	Exterior view, looking generally north from the building, viewing the backs of the houses that are along Main Street in the lower section of Slatington. (61 View north 1.tif)	north
62	Exterior view, looking generally north from the building, viewing the backs of the houses that are along Main Street in the lower section of Slatington. (62 View north 2.tif)	north
	along Main Street in the lower section of Statington. (62 View north 2.111)	

	Key #	_
ER#_		

# Site Plan (Item 34)

See the Instructions for more information regarding the site plan. Create a sketch of the property, showing the footprint of all buildings, structures, landscape features, streets, etc. Label all resources and streets. Include a North arrow and a scale bar (note if scale is approximate). This sheet may be used to sketch a plan or another map/plan may be substituted.

	Key #	
ER#		_

# Floor Plan (Item 35)

See the Instructions for more information regarding the floor plan. Provide a floor plan for the primary buildings, showing all additions. Label rooms and note important features. Note the date of additions. Include a North arrow and a scale bar (note if scale is approximate) or indicate width/depth dimensions. This sheet may be used to sketch a floor plan or another map/plan may be substituted.

substitutea.		

	Key #	
ER#		

#### Physical Description and Integrity (Item 38)

Provide a current description of the overall setting, landscape, and resources of the property. See page 13 of the Instructions for detailed directions. Continue on additional sheets as needed. Suggested outline for organizing this section:

- Introduction [summarize the property, stating type(s) of resource(s) and function(s)]
- Setting [describe geographic location, streetscapes, natural/man-made landscape features, signage, etc.]
- Exterior materials, style, and features [describe the exterior of main buildings/resources]
- Interior materials, style, and features [describe the interior of main buildings/resources]
- Outbuildings/Landscape [describe briefly additional outbuildings/landscape features found on property, substitute Building Complex Form if preferred; See Instructions, page 18]
- Boundaries [explain how/why boundaries chosen, such as historic legal parcel, visual natural features such as tree lines, alley separating modern construction, etc.]
- Integrity [summarize changes to the property and assess how the changes impact its ability to convey significance

(Text entered directly into form fields will not permit formatting adjustments, such as spell checking or italicizing. Instead, you may wish to cut-and-paste text from another document into the field below; "unprotect" the document for this section; or prepare the "Physical Description and Integrity" narrative as a separate document.)

	Key #	
ER#		

### **History and Significance** (Item 39)

Provide an overview of the history of the property and its various resources. Do not substitute deeds, chapters from local history books, or newspaper articles. See page 14 of the Instructions for detailed directions. Continue on additional sheets as needed. Suggested outline for organizing this section:

- History [Summarize the evolution of the property from origin to present]
- Significance [Explain why the property is important]
- Context and Comparisons [Describe briefly similar properties in the area, and explain how this property compares]

(Text entered directly into form fields will not permit formatting adjustments, such as spell checking or italicizing. Instead, you may wish to cut-and-paste text from another document into the field below; "unprotect" the document for this section; or prepare the "History and Significance" narrative as a separate document.)